

# **APPENDIX F.1**

## Hazardous Materials

**Table F-1 - Direct Route Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
Section 1 0 - 0.5 mile	15	Southampton Village Highway Willow Street	Northern adjacent	Closed Status Spill	During tank removal, 8 yards of gasoline-contaminated soil was removed. Closed status as of 04/19/1990	<ul style="list-style-type: none"> <li>• Map ID # 1,4,16-20,31-40,63,68,69,88 &amp; 102. Southampton Coal &amp; Produce / Petro Inc / Giffords Oil, 224 Main Street (&lt;1/8 mile north) This Major Oil Facility / Petroleum Bulk Storage Site has the following ASTs: 300,000-gallon, 123,000-gallon, (3) 20,000-gallon, (2) 550-gallon, (2) 275-gallon &amp; (2) 278-gallon. An active tank failure was reported on 06/05/07 resulting in the release of #2 fuel oil. Fifteen closed status spills have been reported for the site, including affected groundwater.</li> <li>• Map ID #3 Exxon, 13 County Road 39 (&lt;1/2 mile west). A release of unknown quantity of gasoline was reported on 05/08/07. The site is considered an Active Haz Spill.</li> <li>• Map ID #7 Chabad Residence, 40 Winding Way (&lt;1/8 mile north). A release of an unknown quantity of #2 fuel oil due to equipment failure was reported on 07/03/07. The site is considered an Active Haz Spill.</li> <li>• Map ID #8 Unknown, 50 Schwenck Road (&lt;1/2 mile north). A release of approximately 20 gallons of transformer oil due to a traffic accident was reported on 03/01/07. The site is considered an Active Haz Spill.</li> </ul>	<ul style="list-style-type: none"> <li>• Commercial area, including Gulf Service Station &amp; Mobil Service Station</li> </ul>	<ul style="list-style-type: none"> <li>• 1895 • 1902 • 1909 • 1920 • 1926 • 1931 • 1932 • 1945 • 1947 • 1964</li> <li>• Residential and commercial area</li> </ul>	<ul style="list-style-type: none"> <li>• 1955 • 1966 • 1978 • 1984 • 1996</li> <li>• Residential &amp; commercial area</li> </ul>
	64			Petroleum Bulk Storage Site	A total of 10 tanks were removed from the site. (2) 6,000-gallon USTs, (1) 550-gallon UST, (1) 275-gallon AST and drum storage are present at the site.				
	30	Westerhoff Residence 35 Prospect Street	Eastern adjacent	Closed Status Spill	Approximately one gallon of #2 fuel oil was released on the concrete basement floor. The site was cleaned and closed on 01/18/95.				
Section 2 0.5 - 3 mile	17	Southampton Railroad Station North Main Street	On Site	Closed Status Spill	150 gallons of diesel fuel was released due to a traffic accident. The site was closed on 05/24/1996	<ul style="list-style-type: none"> <li>• Commercial area</li> <li>• Residential and undeveloped land</li> </ul>	No coverage	<ul style="list-style-type: none"> <li>• 1955 • 1966 • 1978 • 1984 • 1996</li> <li>• Agricultural, residential &amp; undeveloped area</li> </ul>	
	24			Closed Status Spill	An unknown quantity of diesel fuel was released due to a traffic accident. The site was closed on 09/30/97.				
	100			Hazardous Waste Generator / Transporter	300 pounds and 25 cubic yards of lead were generated in 2003.				
	54	Southampton Lumber Corporation 21 Powell Avenue	Southern adjacent	Petroleum Bulk Storage Site	(2) 1000-gallon and (1) 4000-gallon USTs were removed on 11/21/1990.				
	104	Southampton Collision 21 Plant Street	Southern adjacent	Hazardous Waste Generator / Transporter	110 gallons and 1584 pounds of spent non-halogenated solvents were generated in 1991 and 1987, respectively.				
	56	Briam Meringola 224 David Whites Lane	Southern adjacent	Petroleum Bulk Storage Site	No additional information available.				
	52	Randalls Auto Collision Inc 277 David Whites Lane	Southern adjacent	Petroleum Bulk Storage Site	No additional information available.				
	101			Hazardous Waste Generator / Transporter	85 gallons and 90 gallons of non-halogenated solvents were generated in 1996 and 1990, respectively. 60 gallons of ignitable solid waste was generated in 1987.				
	1			Active Tank Failure	A release of #2 fuel oil from a leaking UST was reported on 11/18/05.				
	20	Unknown David Whites Lane	On Site	Closed Status Spill	A release of lube oil was cleaned and closed as of 01/27/04.				
	30	LILCO Southampton Gas Turbine Site David Whites Lane	Eastern adjacent	Closed Status Spill	A release of 200 gallons of kerosene was cleaned and closed on 12/24/99.				
	31			Closed Status Spill	A release of lube oil and waste/used oil was cleaned a closed as of 07/6/98.				
	32			Closed Status Spill	A release of 20 gallons of fuel additive was cleaned an closed on 12/12/86.				
	55			Petroleum Bulk Storage Site	(2) 275-gallon USTs were removed in 1985. (1) 125,000-gallon UST, (1) 500-gallon UST, (2) 550-gallon USTs, (1) 6,700-gallon AST, (1) 120-gallon AST, (1) 1,700-gallon AST, (1) 100-gallon AST and drum storage are present at the site.				
	102			Hazardous Waste Generator / Transporter	110 gallons of material having characteristics of ignitability was generated in 2001.				
	117			Chemical storage facility	Naphthalene is stored in 250-gallon AST at this waste water treatment plant.				
	119			Wastewater discharge facility	The facility is permitted to release wastewater to groundwater.				
	2			Active Haz Spill	A release of two gallons of lube oil was reported on 12/03/02. The product was found in a monitoring tube. No cleanup needed.				
	121			Air Discharge Site	Air discharge permits for the facility include total hydrocarbons, nitrogen dioxide, total particulate matter & sulfur dioxide.				
				Closed Status Spill	A release of ten gallons of #2 fuel oil was cleaned and closed as of 9/15/88.				
25	Benkoski Cty Road 39 / David Whites Lane	On Site	Closed Status Spill	A release of diesel fuel from a generator was cleaned and closed as of 06/12/92.					
26	CSC acquisition Cty Road 39 / David Whites Lane	On Site	Closed Status Spill	A release of diesel fuel was cleaned and closed as of 4/16/92.					
28	MYSTIC Route 27	On Site	Closed Status Spill	A release of 15 gallons of #2 fuel oil was cleaned and closed on 12/24/90.					
29	Southampton Gt Cty Road 39 / David Whites Lane	On Site	Closed Status Spill	A release of fuel oil was cleaned and closed as of 2/9/04.					
18	James Lynch Inc. 375 David Whites Lane	Southern adjacent	Closed Status Spill	A release of gasoline was cleaned and closed on 6/19/91.					
53			Petroleum Bulk Storage Site	(3) 1000-gallon USTs were removed on 12/19/90.					
103			Hazardous Waste Generator / Transporter	55 gallons of material having characteristic of ignitability were generated in 1991.					
19	Berkosk Ice 30 Lower Seven Ponds Road	Northern adjacent	Closed Status Spill	A release of waste oil / used oil was cleaned and closed as of 08/30/95.					

**Table F-1 - Direct Route Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
Section 3 3 - 9.5 mile	31	Chips's Auto Repair 610 Scuttle Hole Road	Southern adjacent	Petroleum Bulk Storage Site	280 gallon waste oil AST is reported to be awaiting construction.	• Map ID# 10 Sag Harbor S/S, 1434 Sag Harbor Turnpike (<1/2 mile north). A release of an unknown quantity of hydraulic oil due to equipment failure was reported on 05/19/04. The site is considered an Active Haz Spill.	• Residential and undeveloped land • Commercial area, including Sag Harbor Landfill	No coverage	• 1955 • 1966 • 1978 • 1984 • 1996 • Agricultural, residential & commercial area, including landfill
	32			Petroleum Bulk Storage Site	No additional information available.				
	56			Hazardous Waste Generator / Transporter	150 gallons of lead was generated in 1993.				
	7	Stafford Residence 680 Scuttle Hole Road	Northern adjacent	Active Tank Failure	A release from a UST no longer in use in a basement was reported on 07/21/05. No further information was available.				
	19	Unknown Scuttle Hole Road / Hayground	On Site	Closed Status Spill	40 gallons of hydraulic oil was spilled affecting the soil. Closed on 2/12/1999				
	33	Gordon Farm Scuttle Hole Road	On Site	Petroleum Bulk Storage Site	1000-gallon gasoline AST awaiting construction				
	34	Channing Daughters Winery 1927 Scuttle Hole Road	Northern adjacent	Petroleum Bulk Storage Site	No additional information available.				
	35	Ronnies Auto Body Bridgehampton Sag Harbor	Northern adjacent	Petroleum Bulk Storage Site	No additional information available.				
	20	LILCO Sag Harbor Turnpike / Scuttle Hole	On Site	Closed Status Spill	A release of two gallons of transformer oil was cleaned and closed on 09/12/88.				
	21	LILCO Sag Harbor Turnpike / Scuttle Hole	On Site	Closed Status Spill	A release of one gallon of non-PCB oil was cleaned and closed on 04/01/96.				
	57	Long Island Lighting Co 1000 Montauk Highway	On Site	Hazardous Waste Generator / Transporter	2766 gallons of PCB-containing liquid was generated in 1991. 1972 kilograms of PCB-containing material was generated in 1995.				
	3, 4, 5 & 6	Sag Harbor Transfer Station Sag Harbor Turnpike	Eastern adjacent	Solid Waste Facility	Transfer station permits include the following waste categories: residential, mixed solid waste, recyclables & waste oil.				
	59			Hazardous Waste Generator / Transporter	The following waste was generated in 1986: 62 gallons & 113 pounds of ignitable solid waste, 29 gallons & 20 pounds of corrosive solid waste, 2 gallons of chromium, 6 gallons of mercury, 3 gallons of chlordane & 14 pounds of benzene.				
	36			Petroleum Bulk Storage Site	(1) 300-gallon waste oil AST is present at the site.				
	22			Closed Status Spill	Waste oil was released from an overfilled tank. The site was cleaned and closed as of 10/20/04.				
	1			NYSDEC Inactive Haz Waste Disposal Site	The transfer station has reportedly been in operation since 1950. The potential exists for groundwater contamination since no subsurface liner or leachate system exist. However, no hazardous waste disposal has been documented for this site.				
2	CERCLIS Superfund NFRAP Site	The site is assigned EPA Facility ID NYD980762637. No further action is planned.							

Table F2 - Underground Alternative Environmental Issues									
Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
	25	Lonski Residence 270 North Sea Road	On Site	Closed Status Spill	A release of #2 fuel oil was found in the basement, 20 yards of contaminated debris was removed. Closed status as of 10/11/2000.	* Map ID #2, 12, 31, 33-36, 76-85, 104, 149-151, 188&204. Southampton Coal & Produce / Petro Inc / Giffords Oil, 224 Main Street (~1/8 mile north) This Major Oil Facility / Petroleum Bulk Storage Site has the following ASTs: 300,000-gallon, 123,000-gallon, (3) 20,000-gallon, (2) 550-gallon, (2) 275-gallon & (2) 278-gallon. An active tank failure was reported on 06/05/07 resulting in the release of #2 fuel oil. Fifteen closed status spills have been reported for the site, including affected groundwater.	• Commercial area, including Gulf Service Station & Mobil Service Station	• 1895 • 1902 • 1909 • 1920 • 1926 • 1931 • 1932 • 1945 • 1947 • 1964 • Residential and commercial area	• 1955 • 1966 • 1978 • 1984 • 1996 • Residential & commercial area
	44	County Road 39 and North Sea Road	On Site	Closed Status Spill	A release of transformer oil was reported due to a traffic accident. Closed status as of 01/13/97.				
	45	Southampton Tire County Road 39 and North Sea Road	On Site	Closed Status Spill	Anti-freeze, waste oil, and calcium chloride were released due to poor housekeeping. Closed status as of 05/29/98.				
	46	Unlimited Cement Corp County Road 39 and North Sea Road	On Site	Closed Status Spill	Waste oil was released during an oil change. Closed status as of 05/19/97.				
	50	McDonalds Perske Trucking County Road 39 and North Sea Road	On Site	Closed Status Spill	Approximately 100 gallons of diesel fuel were released from a fractured tank in a traffic accident. Area was diked and remediated. Closed status as of 02/06/91.				
	53	Unknown County Road 39 and North Sea Road	On Site	Closed Status Spill	Approximately 50 gallons of diesel fuel was released due to a traffic accident. Area was sanded and cleaned by the county. Closed status as of 09/09/86.				
	56	County Road 39 and North Sea Road	On Site	Closed Status Spill	Non-PCB transformer oil was released due to a traffic accident. Closed status as of 12/11/00.				
	57	County Road 39 and North Sea Road	On Site	Petroleum Bulk Storage Site	A release of gasoline was reported due to a traffic accident. Closed status as of 06/08/00.				
	173	Silver Perry L. DDS 320 North Sea Road	East and South	Hazardous Waste Generator / Transporter	No additional information was available for this site.				
	6	Exxon Mobil Service Station 13 County Road 39	West Adjacent	Active Haz Spill	Leaking dispenser valves on pumps #1 and #6 were shut down for repairs on 05/08/07				
	26			Closed Status Spill	A leak alarm was activated and reported on 08/03/94. Closed status as of 02/09/01.				
	59			Closed Status Spill	A leaking pump nozzle was reported on 05/13/94. Closed status as of 05/16/94.				
	110			Closed Status Spill	(10) USTs were previously removed from the site. (1) 10,000-, (1) 12,000-, and (2) 6,000-gallon gasoline and (1) 1,000-gallon #2 fuel oil UST are present at the site.				
	177			Hazardous Waste Generator / Transporter	No additional information was available for this site.				
	47	B&L Coastal Service Station 380 North Sea Road	East and South Adjacent	Closed Status Spill	(4) Illegally removed USTs were reported on 07/20/93. Closed status as of 11/10/93.				
	106			Petroleum Bulk Storage Site	(4) USTs were previously removed from site. (2) 10,000-gallon gasoline and (1) 8,000-gallon diesel fuel USTs are present at the site.				
	58	Squires Residence 379 North Sea Road	West Adjacent	Closed Status Spill	A release of #2 fuel oil due to human error was reported on 11/11/93. Closed status as of 11/19/93.				
	19	Gulf Service Station/Cumberland Farms 10 County Road 39	West Adjacent	Closed Status Tank Test Failure	A tank test failure was reported on 05/16/05. Closed status as of 07/28/05.				
	20			Closed Status Tank Test Failure	A tank test failure was reported on 05/16/05. Closed status as of 07/28/05.				
	21			Closed Status Tank Test Failure	A tank test failure was reported on 04/13/05. Closed status as of 05/01/05.				
	27			Closed Status Spill	A leak due to tank test failure was reported on 06/03/03. Closed status as of 08/29/06.				
	60			Closed Status Spill	A release of approximately 10 gallons of diesel fuel was reported on 01/22/93. Closed status as of 01/25/93.				
	108			Petroleum Bulk Storage Site	(3) USTs were previously removed from site. (3) 10,000-gallon gasoline, (1) 2,500-gallon diesel fuel, and (1) 500-gallon kerosene USTs are present at the site.				
	176			Hazardous Waste Generator / Transporter	No additional information was available for this site.				
	109	Snow White Laundry 50 County Road 39	South Adjacent	Petroleum Bulk Storage Site	(1) 750-gallon UST containing #2 fuel oil was removed on 01/06/05.				
	175			Closed Status Tank Test Failure	60 pounds of spent halogenated solvent was generated in 2003.				
	200			Wastewater Discharge Facility	Laundry & Garment Services with minor wastewater discharge is listed as inactive.				
	105	Ed Sidor Photo 77 County Road 39	North Adjacent	Petroleum Bulk Storage Site	No tank information was reported for this site.				
	172			Hazardous Waste Generator / Transporter	275 gallons & 200 pounds of silver were generated in 2003 & 1994, respectively. 55 gallons of ignitable solid waste was generated.				
	55	County Road and North Main Street	South Adjacent	Closed Status Spill	A release of motor oil due to a traffic accident was reported and closed on 02/26/02.				

Table F2 - Underground Alternative Environmental Issues									
Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
	114	Andrew De Weil Inc County Road 39	North Adjacent	Petroleum Bulk Storage Site	(3) USTs were previously removed from site. (1) 500-gallon and (3) 250-gallon #2 fuel oil ASTs are present at the site.				
	112	Lexus of Southampton 299 County Road 39	North Adjacent	Petroleum Bulk Storage Site	(1) 250- and (2) 280-gallon ASTs containing motor oil and waste oil are present at the site.				
	111	Southampton Car Wash Inc 404 County Road 39	South Adjacent	Petroleum Bulk Storage Site	No additional information was available for this site.				
	201			Wastewater Discharge Facility	The site's first permit for car wash discharge was given on 04/27/00.				
	7	Hampton Jitney 395 County Road 39	North Adjacent	Active Haz Spill	Contaminated soil was discovered during a 5000-gallon diesel fuel tank removal.				
	22			Closed Status Tank Test Failure	A tank test failure was reported on 04/04/89. Closed status as of 07/03/89.				
	62			Closed Status Spill	Runoff into storm drains during engine cleaning was reported and closed on 02/11/02.				
	113			Petroleum Bulk Storage Site	(4) USTs were previously removed from site. Drum storage, 1000-, 2,000-, 3,000-, 7,000-, and 12,000-gallon USTs and 1000-, 500-, (3) 280-gallon ASTs are present at the site.				
	48	Benkoski Country Road 39 / David Whites Lane	North Adjacent	Closed Status Spill	A release of diesel fuel from a generator was cleaned and closed as of 06/12/92.				
	49	CSC Acquisition Country Road 39 / David Whites Lane	North Adjacent	Closed Status Spill	A release of diesel fuel was cleaned and closed as of 4/16/92.				
	51	LILCO Country Road 39 / David Whites Lane	North Adjacent	Closed Status Spill	A release of #2 fuel oil from a tank truck was reported on 08/22/88. Closed status as of 09/05/88.				
	52	MYSTIC Off Route 27	North Adjacent	Closed Status Spill	A release of 15 gallons of #2 fuel oil was cleaned and closed on 12/24/90.				
	54	Southampton GT Country Road 39 / David Whites Lane	North Adjacent	Closed Status Spill	A release of fuel oil was cleaned and closed as of 2/9/04.				

**Table F-3 - Existing Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review	
Section 1 0 - 1 mile	40	LILCO Prospect Street & North Sea Road	On Site	Closed Status Spill	A spill of PCB-containing oil was reportedly cleaned & closed on 11/26/86.	<ul style="list-style-type: none"> <li>Map ID #1,9,24,26-29,43-52,89,99,100,14 &amp; 158.</li> <li>Southampton Coal &amp; Produce / Petro Inc / Giffords Oil, 224 Main Street (&lt;1/4 mile north). The following ASTs are currently reported at this Major Oil Facility / Petroleum Bulk Storage Site: 300,000-gallon, 123,000-gallon, (3) 20,000-gallon, (2) 550-gallon, (2) 275-gallon &amp; (2) 278-gallon. An active tank failure was reported on 06/05/07 resulting in the release of an unknown quantity of #2 fuel oil. Fifteen closed status spills have been reported for the site, including affected groundwater.</li> </ul>	<ul style="list-style-type: none"> <li>Commercial area, including Gulf Service Station &amp; Mobil Service Station</li> </ul>	<ul style="list-style-type: none"> <li>1895 • 1902 • 1909 • 1920 • 1926 • 1931 • 1932 • 1945 • 1947 • 1964</li> <li>Residential and commercial area</li> </ul>	<ul style="list-style-type: none"> <li>1955 • 1966 • 1978 • 1984 • 1996</li> <li>Residential &amp; commercial area</li> </ul>	
	137	Long Island Lighting Company Prospect Street & North Sea Road	On Site	Hazardous Waste Generator / Transporter	6346 gallons of PCB-containing liquid was generated in 1991. 5000 kilograms of PCB-containing material was generated in 1996.					
	22	Southampton Village Highway Dept., 102 Willow Street	Northern & western	Closed Status Spill	Petroleum-contaminated soil was removed during a UST removal. Closed status as of 04/19/90.					
	91	Southampton Village Highway Dept, 102 Willow Street	Northern & western adjacent	Petroleum Bulk Storage Site	(6) USTs & (3) ASTs were previously removed from the site. (2) 6,000-gallon USTs, (2) 550-gallon USTs, (1) 275-gallon AST & drum storage are present at the site.					
	95	Snow White Laundry 50 County Road 39	Western adjacent	Petroleum Bulk Storage Site	(1) 750-gallon UST containing #2 fuel oil was removed on 01/06/05.					
	139				Hazardous Waste Generator / Transporter					60 pounds of spent halogenated solvent was generated in 2003.
	157				Wastewater Discharge Facility					Laundry & Garment Services with minor wastewater discharge is listed as inactive.
	90	Ed Sidor Photo 77 County Road 39	Western adjacent	Petroleum Bulk Storage Site	No tank information was reported for this site.					
	138				Hazardous Waste Generator / Transporter					275 gallons & 200 pounds of silver were generated in 2003 & 1994, respectively. 55 gallons of ignitable solid waste was generated in 1997.
92	SCWA Long Springs Road				Eastern adjacent	Petroleum Bulk Storage Site	(1) 550-gallon UST was previously removed from the site. (2) 640-gallon ASTs & (2) 550-gallon ASTs remain at the site.			
Section 2 1 - 8.4 mile	43	Long Island Lighting Company Bridgehampton Sag Harbor TPKE	On Site	Hazardous Waste Generator / Transporter	2766 gallons of PCB-containing liquid was generated in 1991. 1972 kilograms of PCB-containing material was generated in 1995.	<ul style="list-style-type: none"> <li>Map ID #7 Sag Harbor S/S, 1434 Sag Harbor Turnpike (&lt;1/2 mile north). A release of an unknown quantity of hydraulic oil due to equipment failure was reported on 05/19/04. The site is considered an Active Haz Spill.</li> </ul>	<ul style="list-style-type: none"> <li>Residential and undeveloped land</li> <li>Commercial area, including Sag Harbor Landfill</li> </ul>	No coverage	<ul style="list-style-type: none"> <li>1955 • 1966 • 1978 • 1984 • 1996</li> <li>Agricultural, residential &amp; commercial area, including landfill</li> </ul>	
	3,4,5 & 6	Sag Harbor Landfill Sag Harbor Transfer Station Bridgehampton Sag Harbor TPKE	Eastern adjacent	Solid Waste Facility	Transfer station permits include the following waste categories: residential, mixed solid waste, recyclables & waste oil.					
	36			Petroleum Bulk Storage Site	(1) 300-gallon AST containing waste oil is registered at the site.					
	44			Hazardous Waste Generator / Transporter	2 gallons of chromium, 6 gallons of mercury, 3 gallons of chlordane, 14 pounds of benzene, 91 gallons of ignitable solid waste & 133 pounds of ignitable solid waste were generated in 1986.					
	18			Closed Status Spill	Waste oil was released from an overfilled tank. The site was cleaned and closed as of 10/20/04.					
	1			NYSDEC Inactive Haz Waste Disposal Site	The transfer station has reportedly been in operation since 1950. The potential exists for groundwater contamination since no subsurface liner or leachate system exist. However, no hazardous waste disposal has been documented for this site.					
	2			CERCLIS Superfund NRFAP Site	The site is assigned EPA Facility ID NYD980762637. No further action is planned.					

**Table F-4 - Long Island Railroad Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
Section 1 0 - 1 mile	23	Southampton Village Highway Willow Street	Southern Adjacent	Closed Status Spill	During tank removal, 8 yards of gasoline-contaminated soil was removed. Closed status as of 04/19/1990	<ul style="list-style-type: none"> <li>• Map ID #1, 6, 24-28, 40-49, 80, 84, 85, 132 &amp; 152. Southampton Coal &amp; Produce / Petro Inc / Giffords Oil, 224 Main Street (&lt;1/8 mile north) The following ASTs are currently reported at this Major Oil Facility / Petroleum Bulk Storage Site: 300,000-gallon, 123,000-gallon, (3) 20,000-gallon, (2) 550-gallon, (2) 275-gallon &amp; (2) 278-gallon. An active tank failure was reported on 06/05/07 resulting in the release of an unknown quantity of #2 fuel oil. Fifteen closed status spills have been reported for the site, including affected groundwater.</li> <li>• Map ID #13 Southampton School Bus GA, Old Mill Road/Upper Seven ponds Road (&lt;1/8 mile toward north). The presence of gasoline in the groundwater was reported due to an unknown cause on 03/03/00 and closed on 03/17/07.</li> <li>• Map ID #5 Exxon 13 Cty Road 39 (&lt;1/4 mile north). A release of an unknown quantity of gasoline due to equipment failure was reported on 05/08/07.</li> </ul>	<ul style="list-style-type: none"> <li>• Long Island Railroad tracks</li> <li>• Commercial area, including Gulf Service</li> </ul>	<ul style="list-style-type: none"> <li>• 1895 • 1902 • 1909 • 1920 • 1926 • 1931 • 1932 • 1945 • 1947 • 1964</li> <li>• Long Island Railroad tracks</li> <li>• Residential and commercial area, including lumber, coal &amp; fertilizer companies</li> </ul>	<ul style="list-style-type: none"> <li>• 1955 • 1966 • 1978 • 1984 • 1996</li> <li>• Residential &amp; commercial area</li> </ul>
	81		Southern Adjacent	Petroleum Bulk Storage Site	A total of 10 tanks were removed from the site. (2) 6,000-gallon USTs, (1) 550-gallon UST, (1) 275-gallon AST and drum storage are present at the site.				
	39	Westerhoff Residence 35 Prospect Street	Southern Adjacent	Closed Status Spill	Approximately one gallon of #2 fuel oil was released on the concrete basement floor. The site was cleaned and closed on 01/18/95.				
	22	Southampton Railroad Station North Main Street	On Site	Closed Status Spill	150 gallons of diesel fuel was released due to a traffic accident. The site was closed on 05/24/1996				
	38			Closed Status Spill	An unknown quantity of diesel fuel was released due to a traffic accident. The site was closed on 09/30/97.				
	130			Hazardous Waste Generator / Transporter	300 pounds and 25 cubic yards of lead were generated in 2003.				
	82	Southampton Lumber Corporation 21 Powell Avenue	Southern adjacent	Petroleum Bulk Storage Site	(2) 1000-gallon and (1) 4000-gallon USTs were removed on 11/21/90.				
131	Southampton Collision 21 Plant Street	Southern adjacent	Hazardous Waste Generator / Transporter	110 gallons and 1584 pounds of spent non-halogenated solvents were generated in 1991 and 1987, respectively.					
Section 2 1 3 mile	51	Brian Meringola 224 David Whites Lane	Southern adjacent	Petroleum Bulk Storage Site	No additional information available.	<ul style="list-style-type: none"> <li>• Map ID #2 Henry Casablanca Residence, 155 Upper Seven Ponds Road (&lt;1/4 mile north). A release of #2 fuel oil due to tank failure was reported on 12/29/04. The site is considered an Active Haz Spill.</li> </ul>	<ul style="list-style-type: none"> <li>• Long Island Railroad tracks</li> <li>• Residential and undeveloped land</li> </ul>	No coverage	<ul style="list-style-type: none"> <li>• 1955 • 1966 • 1978 • 1984 • 1996</li> <li>• Agricultural, residential &amp; commercial area</li> </ul>
Section 3 3 5 mile	12	Scuttlehole Road	On Site	Closed Status Spill	A release of diesel fuel due to a traffic accident was cleaned and closed as of 03/19/98.	<ul style="list-style-type: none"> <li>• Map ID #1 Thomas Conklin, hayground avenue (&lt;1/8 mile toward north). A release of gasoline was reported affecting groundwater due to tank failure on 02/17/87 and closed on 09/08/87.</li> </ul>	<ul style="list-style-type: none"> <li>• Long Island Railroad tracks</li> <li>• Residential and undeveloped land</li> </ul>	No coverage	<ul style="list-style-type: none"> <li>• 1955 • 1966 • 1978 • 1984 • 1996</li> <li>• Agricultural, residential &amp; commercial area</li> </ul>
Section 4 5 8.4 mile	22	Bridgehampton Station	On Site	Closed Status Spill	A release of five gallons of lube oil was cleaned and closed as of 06/17/04.	<ul style="list-style-type: none"> <li>• Map ID #8 Sag Harbor S/S, 1434 Sag Harbor Turnpike (&lt;1/2 mile north). A release of an unknown quantity of hydraulic oil due to equipment failure was reported on 05/19/04.</li> </ul>	<ul style="list-style-type: none"> <li>• Long Island Railroad tracks</li> <li>• Residential and undeveloped land</li> <li>• Commercial area, including Sag Harbor Landfill</li> </ul>	<ul style="list-style-type: none"> <li>• 1920 • 1931 • 1947</li> <li>• Long Island Railroad tracks</li> <li>• Residential and commercial area, including lumber, coal &amp; fertilizer companies</li> </ul>	<ul style="list-style-type: none"> <li>• 1955 • 1966 • 1978 • 1984 • 1996</li> <li>• Agricultural, residential &amp; commercial area, including landfill</li> </ul>
	34	Pondview at Bridgehampton Bridgehampton Turnpike	Southern Adjacent	Petroleum Bulk Storage Site	No additional information available.				
	36	Bridgehampton Childcare and Recreation 551 Route 114 Bridgehampton	Southern Adjacent	Petroleum Bulk Storage Site	(2) 275-gallon ASTs containing #2 fuel oil are present at the site.				
	35	Ronnies Auto Body Bridgehampton Sag Harbor	Northern Adjacent	Petroleum Bulk Storage Site	No additional information available.				
	20	LILCO Sag Harbor Turnpike / Scuttle Hole	On Site	Closed Status Spill	A release of two gallons of transformer oil was cleaned and closed on 09/12/88.				
	21	LILCO Sag Harbor Turnpike / Scuttle Hole	On Site	Closed Status Spill	A release of one gallon of non-PCB oil was cleaned and closed on 04/01/96.				
	57	Long Island Lighting Co 1000 Montauk Highway	On Site	Hazardous Waste Generator / Transporter	2766 gallons of PCB-containing liquid was generated in 1991. 1972 kilograms of PCB-containing material was generated in 1995.				
	3, 4, 5 & 6	Sag Harbor Transfer Station Sag Harbor Turnpike	Eastern Adjacent	Solid Waste Facility	Transfer station permits include the following waste categories: residential, mixed solid waste, recyclables & waste oil.				
	60			Hazardous Waste Generator / Transporter	The following waste was generated in 1986: 62 gallons & 113 pounds of ignitable solid waste, 29 gallons & 20 pounds of corrosive solid waste, 2 gallons of chromium, 6 gallons of mercury, 3 gallons of chlordane & 14 pounds of benzene.				
	40			Petroleum Bulk Storage Site	(1) 300-gallon waste oil AST is present at the site.				
	23			Closed Status Spill	Waste oil was released from an overfilled tank. The site was cleaned and closed as of 10/20/04.				
	1			NYSDEC Inactive Haz Waste Disposal Site	The transfer station has reportedly been in operation since 1950. The potential exists for groundwater contamination since no subsurface liner or leachate system exist. However,				
2			CERCLIS Superfund NFRAP Site	The site is assigned EPA Facility ID NYD980762637. No further action is planned.					

**Table F-5 - Montauk Highway Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
Section 1 0 - 1 mile	23	Southampton Village Highway Willow Street	Southern Adjacent	Closed Status Spill	During tank removal, 8 yards of gasoline-contaminated soil was removed. Closed status as of 04/19/1990	• Map ID #1,6,24-28,40-49,80,84,85,132 & 152. Southampton Coal & Produce / Petro Inc / Giffords Oil, 224 Main Street (<1/8 mile north)	• Long Island Railroad tracks • Commercial area, including Gulf Service Station & Mobil Service Station	• 1895 • 1902 • 1909 • 1920 • 1926 • 1931 • 1932 • 1945 • 1947 • 1964	• 1955 • 1966 • 1978 • 1984 • 1996 • Residential & commercial area
	81		Southern Adjacent	Petroleum Bulk Storage Site	A total of 10 tanks were removed from the site. (2) 6,000-gallon USTs, (1) 550-gallon UST, (1) 275-gallon AST and drum storage are present at the site.	The following ASTs are currently reported at this Major Oil Facility / Petroleum Bulk Storage Site: 300,000-gallon, 123,000-gallon, (3) 20,000-gallon, (2) 550-gallon, (2) 275-gallon & (2) 278-gallon. An active tank failure was reported on 06/05/07 resulting in the release of an unknown			
	39	Westerhoff Residence 35 Prospect Street	Southern Adjacent	Closed Status Spill	Approximately one gallon of #2 fuel oil was released on the concrete basement floor. The site was cleaned and closed on 01/18/95.	Map ID #13 Southampton School Bus GA, Old Mill Road/Upper Seven ponds Road (<1/8 mile toward north). The presence of gasoline in the groundwater was reported due to an unknown			
	22	Southampton Railroad Station North Main Street	On Site	Closed Status Spill	150 gallons of diesel fuel was released due to a traffic accident. The site was closed on 05/24/1996	Map ID #5 Exxon 13 City Road 39 (<1/4 mile north). A release of an unknown quantity of gasoline due to equipment failure was reported on 05/08/07.			
	38			Closed Status Spill	An unknown quantity of diesel fuel was released due to a traffic accident. The site was closed on 09/30/97.				
	130			Hazardous Waste Generator / Transporter	300 pounds and 25 cubic yards of lead were generated in 2003.				
	82	Southampton Lumber Corporation 21 Powell Avenue	Southern adjacent	Petroleum Bulk Storage Site	(2) 1000-gallon and (1) 4000-gallon USTs were removed on 11/21/90.				
131	Southampton Collision 21 Plant Street	Southern adjacent	Hazardous Waste Generator / Transporter	110 gallons and 1584 pounds of spent non-halogenated solvents were generated in 1991 and 1987, respectively.					
Section 2 1 - 2.5 mile	56	Brian Meringola 220 David Whites Lane	Southern adjacent	Petroleum Bulk Storage Site	No additional information available.	• Map ID # 7, 11, 46, 47 & 72. Hampton Jitney, 395 Country Road 39 (<1/8 mile north/northwest). A 5,000-gallon tank was removed in 2002 due to petroleum contamination. No further information was available for the Active Haz Spill. A 12,000-gallon tank failed a tank test. After repair, the site was closed as of 07/03/89. A release of #2 fuel oil was cleaned & closed on 03/28/94. Wastewater & sewage was released in the storm drain. Closed status as of 02/11/02 (4) USTs were previously removed from the site. A 7,000-gallon, 3,000-gallon, 1,000-gallon, 2,000-gallon & 12,000-gallon USTs are present at the site. A 880-gallon, 500-gallon, & (3) 280-gallon ASTs are present at the site.	• Commercial area, including car dealerships • Residential land • Agricultural land, including farms and vineyards	No coverage	• 1955 • 1966 • 1978 • 1984 • 1996 • Agricultural, residential & commercial area
	25	Unknown 691 Country Road 39	On Site	Closed Status Spill	A release of oil from a pole-mounted transformer was cleaned and closed as of 11/28/06.				
	52 & 77	Storms Motors Inc Mayo Motors 691 Country Road 39	Northern adjacent	Petroleum Bulk Storage Site	(5) 275-gallon, (2) 250-gallon & (1) 500-gallon ASTs are present at the site.				
				Hazardous Waste Generator / Transporter	55 gallons of ignitable solid waste, 6 pounds of cadmium & 37 pounds of tetrachloroethylene were generated in 1996. 28 gallons of tetrachloroethylene & 36 gallons of cadmium were generated in 2001 & 2000, respectively.				
	27, 54, 57 & 80	Buzz Chew Chrysler Plymouth Dodge 721 County Road 39	Northern adjacent	Closed Status Spill	Approximately 16 gallons of diesel fuel was released and cleaned w/ absorbant pads. The site was cleaned and closed on 04/18/95.				
				Petroleum Bulk Storage Site	(4) 275-gallon ASTs were removed in 1995. (1) 275-gallon waste oil AST and (1) 500-gallon motor oil AST are present at the site.				
				Petroleum Bulk Storage Site	(2) 250-gallon and (3) 500-gallon ASTs are listed for the site. However, three of these are listed as never installed.				
				Hazardous Waste Generator / Transporter	125,000 pounds of 1,4 Dichlorobenzene and 50 gallons of lead were generated in 1996 and 1993, respectively.				
	26, 55 & 78	Clause Commons 2 Montauk Highway	Southeastern adjacent	Petroleum Bulk Storage Site	(2) 2,000-gallon, (3) 3,000-gallon & (1) 550-gallon USTs were removed from the site in 1994.				
				Closed Status Spill	A release of oil from a pole-mounted transformer was cleaned and closed as of 11/28/06.				
				Hazardous Waste Generator / Transporter	1,000 pounds of benzene were generated in 1994.				
	49	Import Realty Ltd Intersection of County Road 39 & Montauk Highway	Northern adjacent	Closed Status Spill	No tank information was reported for this site.				
	13	Four Seasons Inc Intersection of County Road 39 & Montauk Highway	Southern adjacent	Closed Status Spill	A 550-gallon UST & contaminated soil was removed. A 1000-gallon UST was abandoned in place. Case closed as of 08/05/96.				
14	Unknown Intersection of County Road 39 & Montauk Highway	On Site	Closed Status Spill	A release of oil from a pole-mounted transformer was cleaned and closed as of 01/12/01.					
23	Unknown Intersection of County Road 39 & Montauk Highway	On Site	Closed Status Spill	Hydraulic oil from a garbage truck was released due to a traffic accident. The site was cleaned and closed as of 09/24/99					
1, 51 & 76	Country Imports / BMW of Hamptons Country Car Imports 35 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(2) USTs were previously removed from the site. (1) 1,000-gallon, UST, (1) 2,000-gallon, (6) 275-gallon, and (1) 1,000-gallon ASTs are present at the site.					
			Active Tank Failure	A possible leak from the waste oil tank was reported on 11/21/06. No further information was available.					
			Hazardous Waste Generator / Transporter	5 gallons of tetrachloroethylene was generated in 2006					
24	Unknown 60 Montauk Highway	On Site	Closed Status Spill	The saddle tank on a truck was fractured due to a traffic accident. The site was cleaned and closed as of 04/30/04.					
50	Hampton Arrow Services Inc 84 Route 27 Montauk Highway	Southeastern adjacent	Petroleum Bulk Storage Site	No tank information was reported for this site.					
53	Duck Walk Vineyards Route 27	Northwestern adjacent	Petroleum Bulk Storage Site	(1) 250-gallon AST containing diesel fuel is present at the site.					
9	Bud Gorman Residence 504 Cobb Road	Southern adjacent	Closed Status Tank Test Failure	A 1000-gallon tank containing #2 fuel oil was removed from the site. Case closed as of 03/28/97.					



**Table F-5 - Montauk Highway Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
	34	Water Mill Post Office Route 27 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(1) 2,000-gallon UST was removed in 2003. (1) 1,000-gallon UST is present at the site.				
	8	Lee McGann Residence 773 Montauk Highway	Southern adjacent	Closed Status Spill	A stain on the basement floor was cleaned and case closed as of 05/31/95.				
	61	Water Mill Village Cleaners 760 Montauk Highway	Northern adjacent	Hazardous Waste Generator / Transporter	510 pounds of spent halogenated solvents were generated in 2006.				
	44	Chariots of Fire 800 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(1) 275-gallon waste oil AST was removed in 1995. (1) 275-gallon kerosene AST is present at the site.				
	7	Unknown Davids Lane & Montauk Highway	Southern adjacent	Closed Status Spill	No further information was available for this site. The case was closed as of 02/07/86.				
	29	Water Mill Plaza 903 Montauk Highway	Southern adjacent	Petroleum Bulk Storage Site	(1) 1,000-gallon UST and (1) 275-gallon AST containing #2 fuel oil are present at the site.				
	45	Baywoods Nursery Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(1) 1,000-gallon gasoline UST was removed in 1990.				
	63, 31, 32 & 33	Carriage East Strong Supply & Equipment TLT Restoration Windmill Detail 938 Montauk Highway	Northern adjacent	Hazardous Waste Generator / Transporter Petroleum Bulk Storage Site	The site is historically listed as a small quantity generator of hazardous waste. However, no hazardous waste is present. A total of (7) USTs were removed from the site in 1984, 1987 & 1992. (2) 500-gallon USTs and (1) 250-gallon and (1) 275-gallon ASTs containing #2 fuel oil are reported at the site.				
	4, 15, 16 & 30	Strong Oil Co Inc Mobil Gas Station Watermill Fuel Complex 960 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site Closed Status Tank Test Failure Closed Status Spill	(3) 12,000-gallon USTs, (3) 10,000-gallon USTs & (1) 1,000-gallon AST are present at the property. Tank tightness test was failed; however, no contamination was reported. The case was closed on 12/10/06. A release of approximately one gallon of gasoline was cleaned and closed as of 11/03/03. A release of diesel fuel contaminated a dry well. The site				
	64	Long Island Lighting Co 1000 Montauk Highway	Northern adjacent	Hazardous Waste Generator / Transporter	The following waste types have been generated by the site between 1986 and 2006: hazardous solid waste,				
	46	WJ Petty & Sons Inc Route 27 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(1) 550-gallon gasoline UST was abandoned in place in 1984.				
	38	S&P Sanitation Route 27 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(1) 1,000-gallon AST containing diesel fuel is present at the site.				
	9 & 43	Water Mill Lumber / True Value 1110 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site Closed Status Spill	A release of petroleum was reported at the site. Case closed status as of 10/03/00. A 1,000-gallon AST was removed on 03/03/00. A 240-gallon tank is present at the site.				
	17, 18, 35 & 62	Hess Service Station #32479 1138 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site Closed Status Spill Hazardous Waste Generator / Transporter	(1) 10,000-gallon and (2) 12,000-gallon USTs were removed in 1987. (3) 10,000-gallon gasoline USTs are present. Minor releases of gasoline were cleaned and closed as of 04/29/04 and 10/13/03. 500 pounds and 243 gallons of ignitable solid waste was generated in 1993 and 1988, respectively.				
	14	Unknown Scuttlehole Road & Montauk Highway	Southern adjacent	Closed Status Spill	Non-PCB oil from a transformer was released due to a equipment failure. The site was cleaned & closed as of 02/18/03.				
	5, 6, 40, 41 & 65	Sunset Automotive Inc Corrigans 1640 Montauk Highway	Northern adjacent	Closed Status Tank Test Failure Petroleum Bulk Storage Site Hazardous Waste Generator / Transporter	Tank tightness test was failed. No contamination was reported. The case was closed on 07/18/91 (listed twice). Four gasoline USTs were removed by 1990. (3) 550-gallon waste oil USTs were abandoned in place. (1) 550-gallon 50 gallons of lead were generated in 1993.				
	36 & 37	Walentas / Southampton Produce Distribution Montauk Highway	Southern adjacent	Petroleum Bulk Storage Site	(1) 275-gallon gasoline AST was removed in 1989.				
	28 & 39	South Fork Terminal 2141 Montauk Highway	Southern adjacent	Major Oil Storage Facility Petroleum Bulk Storage Site	(2) USTs and (3) ASTs were previously removed. (2) 20,000-gallon, (2) 10,000-gallon, (1) 500,000-gallon (1)420,000-gallon, (4) 275-gallon, (2) 550-gallon & (1) 1,000-gallon ASTs are present at the site. 55 gallons of ignitable solid waste was generated in 1989.				
	66	Maggrett Auto Body Montauk Highway	Northern adjacent	Hazardous Waste Generator / Transporter	55 gallons of ignitable solid waste was generated in 1989.				
	42	WF McCoy Petroleum Products Inc 2148 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	(5) USTs were previously removed from the site. (1) 6,000-gallon and (1) 8,000-gallon USTs are present at the site. A				
	65	Sea Dune Builders Inc Montauk & Halsey Closed SS	Southern adjacent	Hazardous Waste Generator / Transporter	No hazardous waste activity was reported.	• Map ID #8 Williams Residence, 33 Williams Highway (<1/2 mile south). Elevated levels of MTBE were detected in the private well at this residence on 09/26/01. The site is considered an Active Haz Spill.	• Residential and undeveloped land • Commercial area, including Sag Harbor Landfill	• 1920 • 1931 • 1947 • Residential and commercial area, including lumber, coal & fertilizer companies	• 1955 • 1966 • 1978 • 1984 • 1996 • Agricultural, residential & commercial area, including landfill
	23	Unknown Montauk Highway & Butter Lane	Northern adjacent	Closed Status Spill	A UST and petroleum-contaminated soil were removed from site. Case closed as of 02/15/01.				
	41	Gas Station Route 27 Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	Four gasoline USTs were removed in 1989 and one waste oil UST was removed in 1984.				
	27	Louise Meisel Montauk Highway	On Site	Closed Status Spill	Petroleum contaminated soil was removed and the site was closed as of 04/10/89.				
	40	Urban Archaeology Route 27 Montauk Highway	Southern adjacent	Petroleum Bulk Storage Site	(3) 3000-gallon and (2) 275-gallon USTs were removed in 1989.				
	28	Queen of the Rosary Church Montauk Highway	Northern adjacent	Petroleum Bulk Storage Site	A petroleum release occurred due to a leaking fuel line in the basement. Case closed as of 06/13/95.				

**Table F-5 - Montauk Highway Alternative Environmental Issues**

Location	Map ID #	Facility / Address	Distance / Direction	Environmental Issue	Database Review	Other Off-site Environmental Issues	Site Reconnaissance	Sanborn Map Review	Aerial Review
Section 4 5.5 - 8.5 mile	38	CW Pulver Inc Route 27 Montauk Highway	Southern adjacent	Petroleum Bulk Storage Site	(1) 1,000-gallon UST and (1)550-gallon AST were removed from the site in 1984 & 1991, respectively.				
	66	Hampton Press 2426 Montauk Highway	Southern adjacent	Hazardous Waste Generator / Transporter	165 gallons of silver were generated in 1995.				
	7	Commercial Building 2411 Montauk Highway	Northern adjacent	Active Tank Failure	A leaking 550-gallon fuel oil tank was discovered on 04/26/07. Soil clean up was conducted under direction of the Health Department.				
	22	Unknown Main Street & Hull Street	On Site	Closed Status Spill	A released of transformer oil leaked onto a motor vehicle. Case was closed as of 09/25/958.				
	10, 14, 44, 67 & 68	Texaco Service Station / NYSDEC Montauk Highway	Southeastern adjacent	Closed Status Tank Test Failure	A plume of contaminants with high levels of BTEX was identified. Soil vapor extraction and pump and treat systems were installed in 1988. The 60-foot recovery well was reinstalled in 1990. The site was closed as of 03/10/93.				
				Petroleum Bulk Storage Site	(2) 2,000-gallon, (1) 3,000-gallon & (1) 4,000-gallon USTs were removed from the site in 1988. (1) 1,000-gallon #2 fuel oil UST was removed from the site in 1999.				
				Hazardous Waste Generator / Transporter	1150 gallons of ignitable solid waste was generated in 1988.				
	26	Unknown 64 Sag Harbor Turnpike	On Site	Closed Status Spill	Oil from a pole-mounted transformer was released due to a traffic accident. The site was cleaned & closed as of 12/30/99.				
	29	Unknown 155 Sag Harbor Turnpike	On Site	Closed Status Spill	Oil from a pole-mounted transformer was released due to a traffic accident. The site was cleaned & closed as of 09/12/05.				
	39	Pondview at Bridgehampton Bridgehampton Turnpike	Eastern adjacent	Petroleum Bulk Storage Site	No tank information was reported for this site.				
	43	Bridgehampton Childcare & Recreation	Eastern adjacent	Petroleum Bulk Storage Site	(2) 275-gallon #2 fuel ASTs are present at the site.				
	42	Ronnies Auto Body Bridgehampton Sag Harbor	Western adjacent	Petroleum Bulk Storage Site	No tank information was reported for this site.				
	24 & 25	LILCO Sag Harbor Turnpike & Scuddehole	On Site	Closed Status Spill	Oil from a pole-mounted transformer was released twice. The site was cleaned & closed as of 09/12/88 and 04/01/9.				
	69	Long Island Lighting Co 1000 Montauk Highway	On Site	Hazardous Waste Generator / Transporter	2766 gallons of PCB-containing liquid was generated in 1991. 1972 kilograms of PCB-containing material was				
	1, 2, 3, 4, 5, 6, 45 & 71	Sag Harbor Transfer Station Sag Harbor Turnpike	Eastern adjacent	Solid Waste Facility	Transfer station permits include the following waste categories: residential, mixed solid waste, recyclables & waste oil.				
Hazardous Waste Generator / Transporter				The following was generated in 1986: 62 gallons & 113 pounds of ignitable solid waste, 29 gallons & 20 pounds of corrosive solid waste, 2 gallons of chromium, 6 gallons of					
Petroleum Bulk Storage Site				(1) 300-gallon waste oil AST is present at the site.					
Closed Status Spill				Waste oil was released from an overfilled tank. The site was cleaned and closed as of 10/20/04.					
NYSDEC Inactive Haz Waste Disposal Site				The transfer station has reportedly been in operation since 1950. The potential exists for groundwater contamination since no subsurface liner or leachate system exist.					
CERCLIS Superfund NFRAP Site	The site is assigned EPA Facility ID NYD980762637. No further action is planned.								